

The location of the components is well done. However, the thickness of the tracks is completely homogeneous and the thickness of the GND tracks should be at 0.5. In addition, you have placed the wrecked vias on the pins inside the components and that is not very adequate. Finally he has not drawn a filled zone in the rectangle, Associate it to the back layer.