


## Rewiew Otto Kalliorinne



At first glance, the components are well positioned and the routing the traces are well made.

The only thing that could be said is that the cut-out for the PMW3389DM is on top of the component and should be inside.

On the other hand, you have not drawn a filled zone in the rectangle, associate it to the GND net nor for the black layer.